

NORTHSTAR INSURANCE LIMITED
PLUMBING INSPECTION REPORT

Claim Reference: CLM-1002

Date of Inspection: 19 March 2026

Property: 8 Model Town Link Road, Lahore

Inspector: S. Iqbal, Licensed Plumber

FINDINGS

The waste pipe serving the first floor bathroom has been weeping at a compression fitting. There is heavy limescale and green corrosion staining extending approximately 40 centimetres below the joint.

The ceiling below shows established water staining with defined tide marks and blown plaster. Timber joists are darkened and soft to probe.

In my opinion this leak has been present for several months. The deterioration is consistent with gradual seepage rather than any sudden failure.

CONCLUSION

The damage results from a long standing leak and poor maintenance.
Estimated cost of repair is PKR 96,000.