

Run and analysis log chart: in Shower-max Coordinates:

Run Week: 01


Settings: PMT #544, fADC range 1V, PMT HV 1105V



Run and analysis log chart: in Shower-max Coordinates:

Run Week: 02

Settings: PMT #537, HV: 1100V, fADC range 1V



Run Week: 03

Run Week: 03

