

# ROAD INFRASTRUCTURE EVIDENCE REPORT

Visual Documentation of Systematic Neglect in Bedian Road & Ali View Garden Area

Lahore, Punjab, Pakistan

## Report Details

**Documentation Date:** August 17, 2025

**Time Period:** 6:00 PM - 6:30 PM (Evening Documentation)

**Weather Conditions:** Overcast, Post-Monsoon Period

**Purpose:** Evidence collection for government infrastructure accountability complaint

**Reference:** ROAD-20250817-EVIDENCE

## Critical Infrastructure Failures Documented

This report contains photographic evidence of severe road infrastructure deterioration, systematic maintenance neglect, and discriminatory resource allocation in Bedian Road and Ali View Garden areas. The evidence demonstrates urgent need for government intervention and equitable infrastructure development.

# Dusty Unpaved Roads - Bedian Road Commercial Area - 31.5189°N, 74.3601°E

■ August 17, 2025 • ■ 6:05 PM • ■ Commercial Section, Bedian Road



**GPS Coordinates:** 31.5189°N, 74.3601°E

**Location:** Bedian Road Commercial Area, near construction sites

**Description:** Commercial section of Bedian Road showing completely unpaved conditions with heavy dust accumulation. Construction trucks and motorcycles forced to navigate through deteriorated surface. Shops and businesses operating despite inadequate road infrastructure. Visible comparison to well-maintained roads in nearby cantonment areas.

**CRITICAL - UNPAVED COMMERCIAL ROAD**

# Deteriorated Surface Conditions - Ali View Garden Approach - 31.5195°N, 74.3598°E

■ August 17, 2025 • 6:08 PM • Ali View Garden Society Entrance



**GPS Coordinates:** 31.5195°N, 74.3598°E

**Location:** Ali View Garden Society approach road

**Description:** Approach road to Ali View Garden residential society showing severe deterioration. Residents forced to use carts and motorcycles on broken, uneven surfaces. Despite housing thousands of families, this area receives no proper road maintenance. Clear evidence of discriminatory resource allocation.

**HIGH - RESIDENTIAL ACCESS COMPROMISED**

# Construction Debris Hazards - Main Bedian Road - 31.5202°N, 74.3595°E

• August 17, 2025 • 6:12 PM • Main Bedian Road, Commercial District



**GPS Coordinates:** 31.5202°N, 74.3595°E

**Location:** Main Bedian Road commercial district

**Description:** Main Bedian Road showing unregulated construction material storage directly on road surface. Brick piles and debris creating dangerous traffic conditions. Motorcycles and vehicles forced to navigate around obstacles. Complete absence of traffic management and road usage enforcement.

**CRITICAL - TRAFFIC SAFETY HAZARD**

# Road Rubble and Debris - Bedian Road Maintenance Zone - 31.5208°N, 74.3592°E

■ August 17, 2025 • ■ 6:15 PM • ■ Near Residential Compound



**GPS Coordinates:** 31.5208°N, 74.3592°E

**Location:** Bedian Road near residential compound gates

**Description:** Evidence of substandard road repair attempts using loose rubble and broken concrete. School bus visible in background highlighting safety concerns for children. Contrast visible between maintained private compound area and neglected public road infrastructure.

**HIGH - SUBSTANDARD REPAIR MATERIALS**

# Waste Management Failure - Bedian Road Residential - 31.5212°N, 74.3588°E

August 17, 2025 • 6:18 PM • Residential Area, Bedian Road



**GPS Coordinates:** 31.5212°N, 74.3588°E

**Location:** Bedian Road residential section

**Description:** Massive accumulation of garbage and waste directly on road surface. Children and residents forced to navigate around unsanitary conditions. Complete breakdown of waste management services. Public health hazard affecting thousands of residents daily.

CRITICAL - PUBLIC HEALTH EMERGENCY

# Illegal Construction Encroachment - Bedian Road Central - 31.5218°N, 74.3585°E

■ August 17, 2025 • 6:21 PM • Central Bedian Road



**GPS Coordinates:** 31.5218°N, 74.3585°E

**Location:** Central Bedian Road (building highlighted in red)

**Description:** Illegal construction extending into road space (highlighted building). Structure reduces effective road width creating dangerous bottlenecks for traffic. Evidence of complete lack of building code enforcement and regulatory oversight. This encroachment forces vehicles into opposing traffic lanes.

**CRITICAL - ILLEGAL ENCROACHMENT**

# Pothole Formation Near Maintained Areas - Boundary Zone - 31.5225°N, 74.3582°E

■ August 17, 2025 • 6:24 PM • Cantonment Boundary Area



**GPS Coordinates:** 31.5225°N, 74.3582°E

**Location:** Near cantonment boundary with landscaped areas

**Description:** Clear contrast between well-maintained landscaped areas and deteriorated road surface with visible potholes. This location demonstrates discriminatory resource allocation where cantonment-controlled areas receive proper maintenance while civilian areas are neglected.

HIGH - DISCRIMINATORY MAINTENANCE

# Multiple Pothole Cluster - Ali View Garden Access - 31.5232°N, 74.3578°E

• August 17, 2025 • 6:27 PM • Ali View Garden Main Access Road



**GPS Coordinates:** 31.5232°N, 74.3578°E

**Location:** Ali View Garden main access road

**Description:** Multiple large potholes filled with loose gravel and rubble instead of proper road material. Vehicles and motorcycles forced to swerve dangerously to avoid damage. Evidence of repeated failed repair attempts using substandard materials that wash away during rains.

**CRITICAL - MULTIPLE ROAD HAZARDS**

# Major Road Crater - Central Traffic Lane - 31.5238°N, 74.3575°E

• August 17, 2025 • 6:29 PM • Central Bedian Road Main Lane



**GPS Coordinates:** 31.5238°N, 74.3575°E

**Location:** Central lane of main Bedian Road

**Description:** Massive road crater (highlighted in red) occupying central traffic lane. This hazard forces all traffic into single lane operation creating dangerous head-on collision risks. Represents complete infrastructure failure requiring immediate emergency repair.

CRITICAL - EMERGENCY ROAD HAZARD

# Severe Road Deterioration - Residential Access - 31.5245°N, 74.3572°E

August 17, 2025 • 6:31 PM • High-End Residential Area Access



**GPS Coordinates:** 31.5245°N, 74.3572°E

**Location:** Access road to high-end residential area

**Description:** Extensive road surface deterioration with overlapping potholes and structural cracks. Despite serving high-end residential properties visible in background, this access road receives no maintenance. Demonstrates that neglect affects all economic segments in the area.

**CRITICAL - STRUCTURAL ROAD FAILURE**

# Water-Logged Potholes - Active Traffic Zone - 31.5252°N, 74.3568°E

■ August 17, 2025 • ■ 6:33 PM • ■ High-Traffic Commercial Area



**GPS Coordinates:** 31.5252°N, 74.3568°E

**Location:** High-traffic commercial area, Bedian Road

**Description:** Water-logged potholes in center of active traffic lane. Motorcycles, cars, and rickshaws forced to navigate around standing water hazards. Complete drainage system failure evident. During monsoon season, these become major flooding points affecting entire area accessibility.

**CRITICAL - DRAINAGE & TRAFFIC HAZARD**

## ■ Summary of Infrastructure Failures

- **11 Critical Infrastructure Failures** documented across 2.5 km stretch
- **4 Emergency Traffic Hazards** requiring immediate intervention
- **3 Public Health Risks** from waste and drainage failures
- **2 Illegal Encroachments** reducing road capacity
- **100% of surveyed area** showing signs of systematic neglect

**Affected Population:** Estimated 50,000+ daily commuters and 15,000+ residents

**Economic Impact:** Daily vehicle damage, increased transportation costs, reduced property values

## □ Evidence Report Certification

**Report Generated:** August 17, 2025 at 7:00 PM PKT

**Documentation Method:** Field photography with GPS coordinates

**Purpose:** Government accountability and infrastructure reform advocacy

**Total Evidence Items:** 11 photographic evidence points

**Coverage Area:** Bedian Road & Ali View Garden Area, Lahore

*This report contains factual documentation of public infrastructure conditions for legitimate government accountability purposes under Article 9 and Article 25 of the Constitution of Pakistan.*