

PROJECT

INTRODUCTION TO MATLAB

Prepared For:

AMRO ABDULRAHMAN ABDUIAZIZ

Presented by

Sultan Ibrahim Suleiman 442016618 Aodi Majed Ali Al-Ghamdi 445036853

الرقم الجامعي: 442016618

الاسم: سلطان إبراهيم سليمان رزحان الغامدي.

Engineering College

الاسم: عدى ماجد على الغامدي.

الرقم الجامعي:445036853

Project

```
% Name : Sultan Ibrahim
% Id: 442016618
% Name : Aodi Majed
% Id: 445036853
clear; clc; close all;
% Parameters
PtA = [1, 2]; % Coordinates of point A
R = 3; % Length of the crank
N cyc = 2; % Number of cycles
Trace inc = 20; % Tracing increment
% Define theta (angles in radians)
theta = (1:360) * pi / 180;
% Coordinates of point B
PtB = [PtA(1) + R * cos(theta); PtA(2) + R *
sin(theta)];
% Dimensions of the box at point B
BoxSide = R / 4;
xB1 = PtB(1, :) - BoxSide / 2;
xB2 = PtB(1, :) + BoxSide / 2;
yB1 = PtB(2, :) - BoxSide / 2;
yB2 = PtB(2, :) + BoxSide / 2;
```

```
% Plot settings
figure(1);
hold on;
plot(PtA(1), PtA(2), 'ko', 'MarkerSize', 10,
'MarkerFaceColor', 'k');
axis equal;
axis([PtA(1) - 1.5 * R, PtA(1) + 1.5 * R,
PtA(2) - 1.5 * R, PtA(2) + 1.5 * R]);
pause(0.05);
% Animation loop
for jj = 1:N cyc
    delete(findobj('tag', 'tracer'));
    for ii = 1:length(theta)
        delete(findobj('tag', 'update'));
        % Draw crank
        plot([PtA(1), PtB(1, ii)], [PtA(2),
PtB(2, ii)], 'b-', 'LineWidth', 3, 'tag',
'update');
        % Draw box at point B
        plot([xB1(ii), xB2(ii), xB2(ii),
xB1(ii), xB1(ii)], ...
             [yB2(ii), yB2(ii), yB1(ii),
yB1(ii), yB2(ii)], 'g-', 'LineWidth', 2,
'tag', 'update');
        % Draw point B
        plot (PtB(1, ii), PtB(2, ii), 'bo',
'MarkerSize', 10, 'MarkerFaceColor', 'b',
'tag', 'update');
        % Add tracer
        if rem(ii, Trace inc) == 0
            plot (PtB(1, ii), PtB(2, ii), 'b.',
'tag', 'tracer');
        end
        pause (0.01);
    end
end
```





