

/ task 3: IOT Data Monitoring Dashboard

```
void setup() {  
  Serial.begin(9600);  
  Serial.println("Temperature:,Humidity:");  
}  
  
void loop() {  
  int rawTemp = analogRead(A0);  
  int rawHumidity = analogRead(A1);  
  
  float voltage = rawTemp * (5.0 / 1023.0);  
  float temperatureC = (voltage - 0.5) * 100.0;  
  float humidityPercent = rawHumidity * (100.0 / 1023.0);  
  
  Serial.print(temperatureC);  
  Serial.print(",");  
  Serial.println(humidityPercent);  
  
  delay(500);  
}
```