




G240HVN01.0
BL defect

Date : June.11.'26

Fact & Data

- Customer : OD Hitech
- Model : G240HVN01.0
- Defect symptoms : BL defect
- Defect panel SN : U15A2C73QBZZZS0100 (25/39)
- Defect symptoms :




Junglim's Test picture

Fact & Data

- * We confirmed the issue reported by the customer regarding no image appearing when the screen is turned on.

It was determined that this issue occurred due to the backlight not operating.




The image is displayed.


Fact & Data

- * The backlight driver board has been checked.
- * We confirmed that the fuse is open. (F102 & F101)


Input check (F102)




Input check



Output check



Output check



F101 (Fuse) check

F102 (Fuse) check

Result

1. The fuse in the backlight circuit was confirmed to be in an open condition.
2. As a protective device, the fuse is designed to disconnect when current exceeding its rated limit flows through it.
3. Therefore, this failure is presumed to have been caused by overcurrent in the backlight driving circuit or a short-circuit condition.