


Main Assembly



ASSEMBLY NOTES

- 1. MAX GAP axial float at bearing seat: 0.30 mm
- 2. Check shaft-to-housing CLEARANCE after SA-SEAL-3100 install
- 3. Critical stack: SHA-100 length - HOU-210 bore depth - SA stack

ICD / Functional:

Axial endplay requirement: 0.05 to 0.30 mm

Datums: A = housing mounting face