Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-988478
Estimate date:	5-9-25
Customer:	Jeffrey Brock
Phone:	713-555-1799
Insurance claim:	C-1001
Vehicle:	2017 Honda Civic
VIN:	UF2FM5UY9M09T0450
License plate:	3V 4Z3DFY

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$735.01
Headlamp assembly	1	$514.15
Hood panel	1	$539.86
Body labor	21.8 hrs	$1,481.21
Paint and materials		$620.92
TOTAL		$3,891.15

Appraiser remarks

The vehicle shows damage concentrated on the front driver-side corner, including a cracked bumper cover, a bent headlamp bracket, and a crushed fender with a scuffed hood edge. Most of these marks line up well with the impact described for a left turn into oncoming traffic. The hood and fender panels will be replaced rather than repaired, and the labor hours listed fit the scope of this work. No earlier damage to the vehicle has come to light during inspection. Two similar charges posted to the same day are still under review, and the shop has been asked to send supporting invoices before those items are approved.