Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-752641
Estimate date:	2025-06-23
Customer:	Christopher Shah
Phone:	281-555-0715
Insurance claim:	C-1002
Vehicle:	2013 Jeep Cherokee
VIN:	9RM5VDAZ864ZY1629
License plate:	E19-83F

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,672.22
Left front fender	1	$1,266.79
Headlamp assembly	1	$956.36
Body labor	112.6 hrs	$2,477.00
Paint and materials		$1,508.42
TOTAL		$7,880.79

Appraiser remarks

The vehicle presents front-quarter damage on the driver's side consistent with the reported impact while turning left, including a cracked bumper cover, a bent headlamp bracket and a deformed fender edge. The repair plan calls for replacing the bumper cover, refinishing the fender and recalibrating the sensor. The labor hours requested run roughly three times what this damage normally requires, and I recommend a line-by-line review before approval. Several small scratches on the rear door appear older than this incident and should be excluded from the scope. The billing records show no repeated charges.