Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-428745
Estimate date:	7-8-24
Customer:	Jeffrey Burton
Phone:	346-555-2481
Insurance claim:	C-1004
Vehicle:	2016 Toyota Camry
VIN:	2HEYESE608AX45922
License plate:	4TH1040

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$246.11
Hood panel	1	$263.12
Left front fender	1	$192.58
Body labor	9.7 hrs	$465.32
Paint and materials		$242.94
TOTAL		$1,410.07

Appraiser remarks

The rear quarter panel and left taililght assembly show crush and fracture patterns that line up with the impact described, with the energy running from the rear corner forward along the bumper cover. Repairs proposed include replacing the taillight, refinishing the qurater panel, and straightening the bumper bracket. The estimated labor time runs slightly above what this damage typically requires, so I have asked the shop to review the hour count line by line. Parts pricing and the invoices submitted to date are consistent, with no dpulicate charges. Nothing in the file or the owner's history points to earlier damage on this area of the vehicle.