Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-163929
Estimate date:	2-22-24
Customer:	Kristy Wood
Phone:	346-555-7262
Insurance claim:	C-1005
Vehicle:	2022 Toyota Camry
VIN:	8D1Y5UYN5ECT83216
License plate:	9C 8549P

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,279.76
Trunk lid	1	$1,380.66
Right tail lamp assembly	1	$1,065.69
Body labor	42.1 hrs	$2,859.68
Paint and materials		$1,755.39
TOTAL		$8,341.18

Appraiser remarks

Rear bumper cover cracked and displaced, trunk lid edge deformed, and the left taillight assembly broken, with paint transfer along the rear quarter panel. Some of the lower tail panel damage may or may not stem from this impact, since the pattern is not fully clear from the photos, so that area is flagged for closer review. The repair plan calls for replacing the bumper cover and taillight, straightening the trunk lid edge, and refinishing the affected panels. The labor hours listed fit the damage described. The invoice lines show no repeated charges, and no earlier damage to the vehicle is known from the file or the owner's statement.