Smith Collision Center

4687 James Forge Apt. 980
Baytown, TX
Phone 713-555-0978

Repair Estimate

Estimate number:	EST-765208
Estimate date:	7-3-23
Customer:	Nicole Brown
Phone:	832-555-5990
Insurance claim:	C-1007
Vehicle:	2016 Ford F-150
VIN:	2AHFP1KV6ZU5M6511
License plate:	941AT

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,159.69
Hood panel	1	$724.94
Headlamp assembly	1	$657.79
Body labor	28.0 hrs	$1,902.72
Paint and materials		$877.28
TOTAL		$5,322.42

Appraiser remarks

The vehicle shows scraping and deformation along the right rear quarter panel, extending onto the rear door and bumper cover, with a cracked tail lamp housing and scuffed paint consistent with a sideswipe during a lane change. The damage pattern lines up with the impact as described. Repairs call for panel straightening, replacement of the bumper cover and lamp assembly, and refinishing of the affected panels. The labor hours on the estimate fit the scope of this damage, and the parts and invoices submitted contain no repeated charges. Nothing in the file points to earlier damage on this vehicle.