Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-625882
Estimate date:	20 May 2025
Customer:	Stephanie Jones
Phone:	713-555-1210
Insurance claim:	C-1008
Vehicle:	2022 Jeep Cherokee
VIN:	2T7W2U46962DG4971
License plate:	675-ODK

Estimate details

Description	Qty / Hours	Amount
Rear bumper reinforcement	1	$1,744.14
Right tail lamp assembly	1	$1,410.00
Left tail lamp assembly	1	$1,393.23
Body labor	46.0 hrs	$3,127.11
Paint and materials		$1,536.21
TOTAL		$9,210.69

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken, and the trunk lid edge shows creasing consistent with a straight-on rear impact. The damage pattern matches the impact as described, and no earlier damage to the vehicle is known from prior records. Repair plan calls for replacing the bumper cover and tail lamp assembly, refinishing the trunk lid edge, and recalibrating the rear sensor bracket. The labor hours requested fit the extent of the damage. The invoices submitted show no repeated charges for the same parts or operations.