Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-951767
Estimate date:	6-8-24
Customer:	Stephen Carlson
Phone:	
Insurance claim:	C-1010
Vehicle:	2016 Kia Sorento
VIN:	L667LZDV4KKXV4661
License plate:	868704

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$575.81
Left front fender	1	$527.52
Left quarter panel	1	$342.07
Body labor	18.1 hrs	$1,228.58
Paint and materials		$700.58
TOTAL		$3,374.56

Appraiser remarks

The vehicle presents with damage concentrated on the front driver-side corner, including a cracked bumper cover, a bent headlamp bracket, and a deformed fedner with torn splash shield. Surface scuffing and the pattern of crush align well with the impact described for a left turn into oncoming traffic. Nothing observed suggests prior collision repair, and no earlier damage history has come to light. The proposed repair plan replaces the cover and fender, raeligns the bracket, and refinishes adjacent panels. The labor hours requested match the scope of the work, and the parts and billing lines show no repeated charges. Recommend approval as submitted.