Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-487000
Estimate date:	03/27/2025
Customer:	Chad Richmond
Phone:	346-555-9335
Insurance claim:	C-1011
Vehicle:	2023 Hyundai Elantra
VIN:	M4K5ARMPXNBDD8167
License plate:	SH-4891

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$298.05
Right front door shell	1	$391.70
Left quarter panel	1	$354.57
Body labor	11.8 hrs	$804.65
Paint and materials		$375.84
TOTAL		$2,224.81

Appraiser remarks

Inspection of the vehicle shows scraping and paint transfer along the right rear quarter panel, a cracked rear bumper cover end, and a dented, scuffed right rear door, all consistent with a sideswipe while changing lanes. The damage pattern lines up with the impact as described. The proposed repair plan covers replacing the bumper cover, repairing and refinishing the door and quarter panel, and blending adjacent paint. The labor hours requested fit the extent of the damage. The shop's invoices show no repeated charges. Nothing in the file suggests earlier damage to this vehicle in the same area.