Stein Auto Repair

670 Evans Loaf
Conroe, TX
Phone 281-555-7346

Repair Estimate

Estimate number:	EST-482091
Estimate date:	12/20/2024
Customer:	Steven Lindsey
Phone:	713-555-6204
Insurance claim:	C-1012
Vehicle:	2015 Ford F-150
VIN:	6YNSARR01Y6110834
License plate:	325-722

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,281.66
Hood panel	1	$1,004.54
Left front fender	1	$782.71
Body labor	26.5 hrs	$1,798.89
Paint and materials		$899.82
TOTAL		$5,767.62

Appraiser remarks

Vehicle inspected at the shop following a side impact at an intersection. The primary damage is to the driver-side front door, rear quarter panel, and adjacent sill, with deformation consistent with the reported collision direction. Several light surface scratches on the rear bumper appear older than this loss and are noted separately from the current damage. Repair plan calls for door and panel replacement, refinishing, and sill straightening. The submitted invoices show no duplicated line items, and the labor hours requested match the scope of work described.