Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-821672
Estimate date:	30 May 2024
Customer:	Daniel Smith
Phone:	346-555-8593
Insurance claim:	C-1014
Vehicle:	2016 Ford F-150
VIN:	PBAA18D04UZZM3530
License plate:	XJV-676

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$1,428.98
Hood panel	1	$1,087.96
Left front fender	1	$1,084.68
Body labor	43.9 hrs	$2,982.40
Paint and materials		$1,168.14
TOTAL		$7,752.16

Appraiser remarks

Inspection of the rear bumper cover, left quarter panel and tail lamp assembly shows dmaage consistent with the reported low-speed impact in the parking area. Paint transfer and crush pattern line up with the contact point described, and no prior damage or unrelated repairs are known on this vehicle. The proposed plan is to replace the bumper cover, repair and refinish the quarter panel, and swap the tail lamp, with labor hours that fit the scope of the work. Two similar charges posted on the same day are currently under review and will be confirmed with the shop before pamyent is released.