Carr Auto Repair

841 Joseph Coves
Pearland, TX
Phone 832-555-4935

Repair Estimate

Estimate number:	EST-421308
Estimate date:	7 Nov 2024
Customer:	Kevin Clark
Phone:	281-555-1436
Insurance claim:	C-1015
Vehicle:	2011 Ford F-150
VIN:	BH09HDKA54GU47668
License plate:	Q03 3BI

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$243.15
Right front door shell	1	$208.50
Left quarter panel	1	$138.83
Body labor	8.3 hrs	$562.48
Paint and materials		$242.14
TOTAL		$1,395.10

Appraiser remarks

The vehicle presents rear bumper cover fracture, right quarter panel crease, and a cracked tail lamp housing, all consistent with the low-speed contact reported at the parking lot. The pattern of deformation lines up with the described impact, and no older repair work or prior damage is evident on the panels or fasteners. Proposed repair involves replacing the bumper cover, refinishing the quarter panel, and intsalling a new lamp assembly, with labor hours that fit the extent of the damage. Invoices submitted for the job show no duplicated or repeated charges.