Mendoza Collision Center

47116 Jones Roads
Houston, TX
Phone 281-555-2941

Repair Estimate

Estimate number:	EST-404874
Estimate date:	July 31, 2023
Customer:	William Stone
Phone:	713-555-0143
Insurance claim:	C-1016
Vehicle:	2017 Honda Civic
VIN:	0NTV0ZP34DF2Y2155
License plate:	1KRE 26

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$462.81
Right front door shell	1	$539.11
Left front fender	1	$412.24
Body labor	15.4 hrs	$1,044.00
Paint and materials		$576.40
TOTAL		$3,034.56

Appraiser remarks

The front bumper cover is cracked across the center, and the grille and hood latch bracket are broken. The radiator support shows bending at the left side, and the headlamp assembly is cracked. Some of the lower-frame scuffing may not be from this impact, so the team will verify it before the repair is final. The bills show no repeated charges, and the labor hours fit the damage described. No earlier damage to the vehicle is known. Recommended plan: replace the bumper cover, grille, hood latch, and headlamp, straighten the radiator support, and refinish the front end.