Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-860747
Estimate date:	11-11-23
Customer:	Laurie Gonzales
Phone:	832-555-5982
Insurance claim:	C-1017
Vehicle:	2019 Jeep Cherokee
VIN:	7MTB01H408NDP7634
License plate:	710 0115

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$943.85
Left front fender	1	$964.56
Left quarter panel	1	$835.17
Body labor	33.3 hrs	$2,266.62
Paint and materials		$1,281.19
TOTAL		$6,291.39

Appraiser remarks

The vehicle shows scraping and paint transfer along the right rear quarter panel, with a cracekd tail lamp housing and a bent rear bumper bracket. The pattern and heihgt of the marks are consistent with the reported sideswipe during a lane change, and nothing observed suggests earlier damage to this area. Labor hours for panel straightening, refinishing and lamp replacement are in line with the repairs described. Two similar charges posted on the same day are still under review and have not been confirmed. Repair plan: remove and replace the tail lamp assembly, repair and refinish the quarter panel, and replace the bumper bracket, pending final sign-off on the flagged charges.