Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-291622
Estimate date:	2023-08-19
Customer:	Catherine Cunningham
Phone:	346-555-4178
Insurance claim:	C-1019
Vehicle:	2013 Jeep Cherokee
VIN:	FPNT3Y4W8DH6D2288
License plate:	3DY 901

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$331.49
Headlamp assembly	1	$220.63
Front bumper cover	1	$190.99
Body labor	7.5 hrs	$508.54
Paint and materials		$297.79
TOTAL		$1,549.44

Appraiser remarks

Vehicle inspected at the body shop following a left-turn collision. The damage to the front driver-side quarter panel, bumper cover, and headlamp assembly is largely consistent with the impact described by the insured. Repairs proposed include replacing the bumper cover and headlamp, refinishing the fender, and realigning the mounting brackets. The labor hours listed match the extent of the work required, and the parts and charges on the estimate appear once each with no duplication. No prior damage to this vehicle has come to light in the records reviewed. Recommend approval of the repair plan as submitted.