Williams Auto Body

998 Donovan Ford Suite 346
Pearland, TX
Phone 832-555-7510

Repair Estimate

Estimate number:	EST-937002
Estimate date:	03/29/2024
Customer:	Heather Madden
Phone:	713-555-1266
Insurance claim:	C-1020
Vehicle:	2023 Hyundai Elantra
VIN:	UP0R2ZBM1G50Z2637
License plate:	6-6911Q

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$410.77
Headlamp assembly	1	$268.95
Front bumper cover	1	$180.81
Body labor	9.0 hrs	$610.48
Paint and materials		$266.09
TOTAL		$1,737.10

Appraiser remarks

Inspection of the vehicle confirms damage consistent with a sideswipe to the right rear quarter panel while changing lanes. The rear bumper cover is scuffed and cracked at the right corner, the quarter panel shows a long shallow dent with paint transfer, and the right tail lamp housing is displaced. The damage pattern lines up with the impact as described. Nothing in the file or on the vehicle suggests earlier damage to these areas. The shop's labor hours for panel repair, refinishing, and lamp replacement are reasonable for this scope. Invoices submitted show no repeated charges for the same work. Recommended plan: replace the bumper cover, repair and refinish the quarter panel, and install a new tail lamp assembly.