Jenkins Auto Repair

106 Mcbride Coves
Sugar Land, TX
Phone 281-555-3872

Repair Estimate

Estimate number:	EST-553695
Estimate date:	June 26, 2025
Customer:	Dawn Lewis
Phone:	832-555-7865
Insurance claim:	C-1021
Vehicle:	2016 Kia Sorento
VIN:	B7Y03JS41E3EA4186
License plate:	649 UKZ

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,314.88
Front bumper cover	1	$877.83
Left quarter panel	1	$677.36
Body labor	25.5 hrs	$1,730.72
Paint and materials		$1,104.69
TOTAL		$5,705.48

Appraiser remarks

The vehicle arrived with damage concentrated on the front driver-side corner, including a cracked bumper cover, a deformed fender, a broken headlamp assembly and a bent hood edge. The damage pattern is largely consistent with the impact described, a vehicle turning left into oncoming traffic. Labor hours and parts listed on the estimate match what this damage requires, and the charges on the bill show no repeated entries. Nothing in our records or the owner's account points to earlier damage in these areas. The plan is to replace the bumper cover and headlamp, straighten the fender and hood edge, refinish the affected panels and recheck alignment before release.