King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-694119
Estimate date:	October 15, 2023
Customer:	William Pierce
Phone:	832-555-3540
Insurance claim:	C-1023
Vehicle:	2017 Toyota Camry
VIN:	M6SGELDF68WSW7684
License plate:	0NB64

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$365.36
Right front door shell	1	$336.49
Left quarter panel	1	$293.78
Body labor	10.8 hrs	$737.69
Paint and materials		$318.62
TOTAL		$2,051.94

Appraiser remarks

The rear bumper cover is cracked across its lower center, and the left taillight assembly is broken with the housing pushed inward. Scuffing and paint transfer run along the left quarter panel, which lines up with the reported low-speed contact in the parking lot. Nothing I inspected suggests older damage: the edges are fresh, and no prior repair work is visible. The repair plan calls for replacing the bumper cover, the taillight assembly and the left quarter panel trim, followed by refinishing. The labor hours requested fit the scope of this damage, and the invoices submitted show a single set of charges with no duplicated line items.