Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-524097
Estimate date:	November 3, 2024
Customer:	Erica Holland
Phone:	713-555-0857
Insurance claim:	C-1024
Vehicle:	2022 Hyundai Elantra
VIN:	TMW0ZW0A9ZMH26934
License plate:	0S 98468

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$885.96
Right front door shell	1	$917.15
Left front fender	1	$862.73
Body labor	41.2 hrs	$1,977.90
Paint and materials		$932.67
TOTAL		$5,576.41

Appraiser remarks

The rear quarter panel and bumper cover on the left side show crushed metal, a crcaked lamp housing and scuffing that run in a line consistent with a vehicle turning across the path of oncoming traffic and taking a glancing blow. The damage pattern matches the impact as described. Nothing on the car suggests earlier collision work, and the invoices submitted show no repeated charges for the same parts or tasks. The proposed plan replaces the bumper cover, lamp assembly and rear quarter panel, then refinishes the adjacent surfaces. Labor hours run somewhat high for a repair of this scope, so a line-by-line review of the hours is recommended before approval.