Mcknight Auto Body

993 Hayes Mills Suite 964
Houston, TX
Phone 713-555-3341

Repair Estimate

Estimate number:	EST-498331
Estimate date:	19 Aug 2024
Customer:	Billy Lawrence
Phone:	346-555-0681
Insurance claim:	C-1027
Vehicle:	2018 Honda Civic
VIN:	9380N9FE2HCXM2970
License plate:	HSD 585

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,137.63
Left front fender	1	$918.48
Front bumper cover	1	$830.13
Body labor	23.8 hrs	$1,615.73
Paint and materials		$777.19
TOTAL		$5,279.16

Appraiser remarks

The vehicle presents with damage concentrated on the rear bumper cover, the left quarter panel, and the tail lamp assembly, which is largely consistent with the impact described at the scene. The proposed repair plan calls for replacing the bumper cover, refinishing and blending the quarter panel, and installing a new lamp assembly, with labor hours that match the extent of the damage observed. The repair line items are straightforward, with no duplicated charges appearing on the invoice. Nothing in the file or the owner's history indicates prior damage to these areas, so the scope of work is recommended as submitted.