White Collision Center

342 Patrick Camp Suite 337
Baytown, TX
Phone 832-555-3303

Repair Estimate

Estimate number:	EST-425273
Estimate date:	January 19, 2024
Customer:	Katie Nguyen
Phone:	
Insurance claim:	C-1028
Vehicle:	2019 Honda Civic
VIN:	M0WF78WB7GYMT2641
License plate:	42A-AUCQ

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$493.61
Hood panel	1	$460.52
Left front fender	1	$382.34
Body labor	16.4 hrs	$1,115.21
Paint and materials		$469.51
TOTAL		$2,921.19

Appraiser remarks

Inspection of the front end shows a crushed bumper cover, a cracked grille and a bent radiator support, alnog with a damaged hood latch and cracked headlamp mounts. The pattern of crush and displacement lines up with the frontal impact the claimant described, and the damage sits in the zones a head-on contact would reach. Nothing on the vehicle points to older unrelated damage. The shop's invoices list each operation once with no duplicate charges, and the labor hours are reasonable for replacing and aligning the parts involved. The plan is to replace the bumper cover, grille, radiator support and latch, refit the headlamps, then recheck alignment and cooling system function before release.