Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-435769
Estimate date:	2025-06-20
Customer:	Brandi Miller
Phone:	832-555-1293
Insurance claim:	C-1029
Vehicle:	2017 Honda Civic
VIN:	6FN2NEKG3MYLN1971
License plate:	M32 8NZ

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,731.81
Rear bumper reinforcement	1	$1,104.37
Rear body panel	1	$871.25
Body labor	44.2 hrs	$3,008.27
Paint and materials		$1,468.48
TOTAL		$8,184.18

Appraiser remarks

Rear bumper cover cracked across the center with the left tail lamp housing broken, and the trunk lid edge shows creasing consistent with a straight-on rear impact. The reinforcement bar is bent but not fractured, and the spare tire well shows minor deformation. No prior damage to this vehicle is known, and the paint and panel texture show no signs of older repairs. The reapir plan calls for replacing the bumper cover and lamp, straightening the trunk lid, and refinishing the rear panel, and the labor hours listed fit the scope of this damage. Two similar charges submitted on the same day are currently being reviewed before approval.