Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-188524
Estimate date:	09/04/2024
Customer:	Joe Stephens
Phone:	713-555-7152
Insurance claim:	C-1030
Vehicle:	2015 Chevrolet Malibu
VIN:	3HS8RF8T56NT38785
License plate:	BVS-6568

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$596.50
Hood panel	1	$441.79
Left quarter panel	1	$265.27
Body labor	13.7 hrs	$934.15
Paint and materials		$589.00
TOTAL		$2,826.71

Appraiser remarks

The vehicle presents with damage concentrated on the front driver-side corner, including a cracked bumper cover, a bent headlamp bracket, and a dented fender with a torn support. The pattern of crush and scuffing matches the reported left-turn collision. Repair will involve replacnig the bumper cover and headlamp assembly, straightening the fender, and refinishing the affected panels. The labor hours requested fit the extent of the damage, and the parts list shows no duplicated line items. Nothing observed suggests earlier dmaage to this vehicle.