Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-208210
Estimate date:	3 Feb 2023
Customer:	Mary King
Phone:	281-555-4712
Insurance claim:	C-1031
Vehicle:	2020 Jeep Cherokee
VIN:	D0239NNU8XXF25337
License plate:	D 678719

Estimate details

Description	Qty / Hours	Amount
Rear bumper cover	1	$298.28
Rear body panel	1	$192.90
Trunk lid	1	$142.96
Body labor	12.4 hrs	$593.54
Paint and materials		$338.55
TOTAL		$1,566.23

Appraiser remarks

The rear bumper cover is cracked across the center with the left tail lamp housing broken, and the trunk lid shows a dented edge with paint transfer consistent with the reported impact. The damage pattern lines up with the collision as described. Repair plan calls for replacing the bumper cover and tail lamp assembly, repairing the trunk lid, and refinishing the rear panel. Labor hours look a little high for this scope and should be reviewed against the standard guide. A few older scratches on the lower quarter panel may predate this loss and are noted separately. Two similar charges posted on the same day are currently under review before approval.