Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-520995
Estimate date:	2025-06-04
Customer:	Elizabeth Murillo
Phone:	832-555-0104
Insurance claim:	C-1033
Vehicle:	2024 Nissan Altima
VIN:	53EG6H6C57K1M1811
License plate:	251-WWH

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$1,385.88
Rear bumper reinforcement	1	$1,281.75
Right tail lamp assembly	1	$1,377.68
Body labor	52.4 hrs	$3,561.55
Paint and materials		$1,887.17
TOTAL		$9,494.03

Appraiser remarks

The rear bumper cover is cracked across the center and the left quarter panel shows a crease with paint loss, which fits the rear-end impact described in the claim. The trunk floor pan has a shallow buckle near the spare well, and the tail lamp assembly on the driver side is broken. The plan is to replace the bumper cover, repair and refinish the quarter panel, and install a new tail lamp, with the labor hours matching the extent of this damage. Nothing in the records points to earlier damage to this vehicle, and the charges on the file do not repeat.