Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-395465
Estimate date:	October 26, 2023
Customer:	Paul Oconnor
Phone:	832-555-4100
Insurance claim:	C-1034
Vehicle:	2022 Jeep Cherokee
VIN:	NE53NYSF3SMJT1010
License plate:	FK-3606

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$807.54
Headlamp assembly	1	$913.36
Front bumper cover	1	$843.14
Body labor	26.7 hrs	$1,814.85
Paint and materials		$913.69
TOTAL		$5,292.58

Appraiser remarks

The vehicle was inspected at the shop after a collision that occurred while the insured was turning left. The damage to the front left quarter panel, headlamp assembly, and bumper cover is largely consistent with the impact described. The planned repair involves replacing the bumper cover, refinishing the fender, and recalibrating the driver assistance sensor mounted behind the grille. The labor hours listed on the estimate match the scope of the damage, and the parts line items show no duplicated charges. No prior damage to this vehicle has been reported or found during the inspection. Repairs are recommended to proceed as written.