Patton Collision Center

518 Smith Manor Suite 165
League City, TX
Phone 281-555-6284

Repair Estimate

Estimate number:	EST-696798
Estimate date:	03/28/2025
Customer:	Jessica Walker
Phone:	713-555-9935
Insurance claim:	C-1035
Vehicle:	2010 Ford F-150
VIN:	XRW6G6FH2RV3U9317
License plate:	17L R35

Estimate details

Description	Qty / Hours	Amount
Left front fender	1	$1,665.87
Right front door shell	1	$1,085.97
Hood panel	1	$1,514.46
Body labor	43.6 hrs	$2,962.01
Paint and materials		$1,495.86
TOTAL		$8,724.17

Appraiser remarks

The left rear quatrer panel and rear door on the driver's side show crushed metal and a deep crease that match a side impact at an intersection. Most of the deformation lines up with the reported point of contact. A dated inspection photo on file, however, already shows the same dent before this loss, so that prior damage should be excluded from the repair scope. Labor hours on the estimate fit the remaining damage, and the parts and billing lines contain no repeated charges. Repair plan: replace the rear door shell, repair and reifnish the quarter panel, and recheck alignment of the rear wheel.