Gonzalez Auto Body

27193 Lyons Trafficway
Baytown, TX
Phone 281-555-9912

Repair Estimate

Estimate number:	EST-447843
Estimate date:	6-12-24
Customer:	Thomas Anderson
Phone:	346-555-1103
Insurance claim:	C-1037
Vehicle:	2011 Kia Sorento
VIN:	Z885KEE362LYX6409
License plate:	5KW9062

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$316.40
Left front fender	1	$203.69
Hood panel	1	$133.14
Body labor	8.7 hrs	$418.24
Paint and materials		$205.61
TOTAL		$1,277.08

Appraiser remarks

The rear bumper cover is cracked across its center with the left tail lamp housing broken, and the left quarter panel shows a dent with paint scuffing consistent with the reported contact in the lot. The damage pattern lines up with the impact as described, and I found no sign of older repairs or prior damage on this vehicle. The plan calls for replacing the bumper cover and tail lamp, repairing and refinishing the quarter panel, and a wheel alignment check. The labor hours on the estimate run a little high for this scope, so I have asked the shop to review them. The parts invoices show single entries with no repeated charges.