Henderson Collision Center

17810 Tanya Terrace Apt. 267
League City, TX
Phone 281-555-6026

Repair Estimate

Estimate number:	EST-513901
Estimate date:	6 Aug 2024
Customer:	Mike Roberts
Phone:	713-555-9611
Insurance claim:	C-1038
Vehicle:	2012 Ford F-150
VIN:	ZWEA83XC2UNJN1273
License plate:	

Estimate details

Description	Qty / Hours	Amount
Right front door shell	1	$942.28
Front bumper cover	1	$735.11
Hood panel	1	$507.11
Body labor	30.2 hrs	$1,448.92
Paint and materials		$649.76
TOTAL		$4,283.18

Appraiser remarks

The rear quarter panel and bumper cover on the left side show crushed metal, a cracked lamp housing and scuffing that line up with a vehicle striking the side wihle turning left. The pattern of contact fits the account given and no older damage has come to light. The shop plans to replace the bumper cover, straighten the quarter panel, refinish both areas and fit a new lamp assembly. Parts and paint figures look reasonable on the invoices, which show no duplicated charges. The labor hours appear somewhat high for this scope of work and should be reviewed against standard repair times before approval.