Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-859059
Estimate date:	7-13-23
Customer:	Carol Cox
Phone:	713-555-1471
Insurance claim:	C-1039
Vehicle:	2020 Honda Civic
VIN:	C8MAMPAFXLZCW2280
License plate:	43-U540

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,352.93
Right front door shell	1	$1,633.01
Hood panel	1	$1,204.08
Body labor	41.5 hrs	$2,825.19
Paint and materials		$1,392.06
TOTAL		$8,407.27

Appraiser remarks

The vehicle shows scraping and deformation along the right rear quarter panel, running into the rear door and bumper cover, with a cracked taillight lens and a scuffed wheel arch liner. The pattern of contact fits a sideswipe during a lane change, and the marks are consistent with the impact as described. Repairs call for replacing the bumper cover, straightening and refinishing the rear door, and swpaping the taillight assembly, with labor hours that match the work needed. The line items on the invoice are not duplicated, and no earlier damage to this area is known from prior records. Recommend approval of the repair plan as submitted.