Tucker Collision Center

627 Tina Place Apt. 699
Houston, TX
Phone 713-555-6272

Repair Estimate

Estimate number:	EST-229723
Estimate date:	October 27, 2023
Customer:	Samuel Carter
Phone:	281-555-8073
Insurance claim:	C-1041
Vehicle:	2021 Chevrolet Malibu
VIN:	YN0ZPZSZ0WSF41843
License plate:	007-379

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,199.47
Left front fender	1	$1,068.87
Headlamp assembly	1	$917.97
Body labor	49.4 hrs	$2,369.37
Paint and materials		$1,230.03
TOTAL		$6,785.71

Appraiser remarks

The vehicle presents with damage concentrated on the rear bumper cover, left quarter panel, and tail lamp assembly, which is largely consistent with the reported parking lot impact. Repair plan calls for replacing the bumper cover, refinishing the adjacent panel, and swapping the lamp housing, with a parts review to follow. Invoices revieewd show no duplicated line items. Labor hours appear slightly elevated relative to the scope of visible damage and should be reconciled before approval. Nothing in the file indicates prior damage to this vehicle in the same area.