Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-140526
Estimate date:	4-29-24
Customer:	James Hogan
Phone:	281-555-7340
Insurance claim:	C-1042
Vehicle:	2024 Chevrolet Malibu
VIN:	HXY5JUM35PNV39355
License plate:	BBN 174

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,046.23
Left quarter panel	1	$792.70
Left front fender	1	$726.54
Body labor	25.3 hrs	$1,721.05
Paint and materials		$1,042.85
TOTAL		$5,329.37

Appraiser remarks

The vehicle arrvied with heavy crush and panel displacement along the driver side, including the rear door, quarter panel and rocker area, consistent with a side impact at an intersection. Some of the damage may not stem from this event, as a few older scratches appear weathered and could predate the collision. The repair plan calls for replacing the rear door and quarter panel, straightening the rocker, and refinishing adjacent panels to blend color. Labor hours on the submitted estimate are in line with the extent of the damage observed. The invoices reivewed show no repeated charges for the same operation. Pre-repair photos should be confirmed to separate prior wear from new loss before final approval.