Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

Repair Estimate

Estimate number:	EST-264332
Estimate date:	March 27, 2024
Customer:	Lisa Pierce
Phone:	832-555-3540
Insurance claim:	C-1045
Vehicle:	2011 Kia Sorento
VIN:	
License plate:	ZA9 C1S

Estimate details

Description	Qty / Hours	Amount
Rear body panel	1	$610.53
Trunk lid	1	$672.95
Left tail lamp assembly	1	$705.90
Body labor	21.5 hrs	$1,464.94
Paint and materials		$761.42
TOTAL		$4,215.74

Appraiser remarks

Rear bumper cover cracked and displaced, with the trunk lid edge and right quarter panel showing deformation consistent with a rear-end impact of the reported type. Tail lamp assembly and rear reinforcement bar require replacement, and the spare tire well shows minor crush that can be straightened in place. Labor hours requested align with the extent of the damage observed. The repair plan calls for replacing the bumper cover and lamp assembly, straightening the quarter panel, refinishing the affected panels, and recalibrating the parking sensors. Nothing in the vehicle condition suggests earlier damage in these areas, and the invoices submitted show no duplicated line items.