Osborne Auto Body

870 Samantha Crossing
League City, TX
Phone 281-555-7889

Repair Estimate

Estimate number:	EST-648678
Estimate date:	13 Apr 2024
Customer:	Andrew Ray
Phone:	832-555-9588
Insurance claim:	C-1046
Vehicle:	2011 Hyundai Elantra
VIN:	0RGA4J6S3VJ3P4153
License plate:	MHO 937

Estimate details

Description	Qty / Hours	Amount
Trunk lid	1	$289.74
Rear bumper cover	1	$291.63
Left tail lamp assembly	1	$221.80
Body labor	8.8 hrs	$597.19
Paint and materials		$349.21
TOTAL		$1,749.57

Appraiser remarks

The rear bumper cover is cracked across the center section, with the left tail lamp assembly broken and the trunk lid showing a crease along its lower edge. The damage pattern sits well within what would be expected from the reported rear impact, and the panels affected follow the path of force. Repair will consist of replacing the bumper cover and lamp assembly, straightening and refinishing the trunk lid, and recalibrating the parking sensors. The labor hours requested match the scope of these tasks. No prior damage to this vehicle is known to us, and the invoiced items show no repeated charges.