Stewart Collision Center

727 Green Gateway Suite 873
Katy, TX
Phone 346-555-1434

Repair Estimate

Estimate number:	EST-586598
Estimate date:	4-9-25
Customer:	Heather Nelson
Phone:	281-555-7660
Insurance claim:	C-1047
Vehicle:	2017 Kia Sorento
VIN:	1JBFW7XG4U6WB7214
License plate:	

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,456.08
Left front fender	1	$936.56
Headlamp assembly	1	$1,231.85
Body labor	38.5 hrs	$2,620.64
Paint and materials		$1,620.98
TOTAL		$7,866.11

Appraiser remarks

Rear quarter panel and bumper cover on the driver side show deep crushing and scuffing consistent with a left-turn collision, and the pattern of damage lines up with the impact as described. No earlier damage to the vehicle is known, and the repair labor hours fit the extent of the work needed. Replacement of the bumper cover, refinishing of the quarter panel, and a sensor recalibration are included in the plan. Two similar charges potsed on the same day are currently being checked against the invoice before final approval.