Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-624094
Estimate date:	2023-06-06
Customer:	Yvonne Miller
Phone:	832-555-1643
Insurance claim:	C-1048
Vehicle:	2018 Hyundai Elantra
VIN:	E7R399VK2VBY53303
License plate:	2-44756U

Estimate details

Description	Qty / Hours	Amount
Right tail lamp assembly	1	$1,155.47
Rear body panel	1	$1,530.62
Rear bumper reinforcement	1	$1,162.95
Body labor	63.5 hrs	$3,046.70
Paint and materials		$1,574.58
TOTAL		$8,470.32

Appraiser remarks

The rear bumper cover is cracked and the trunk lid shows a crease along the upper edge, consistent with a rear-end impact. The left taillight assembly is cracked, and the rear quarter panel has a shallow dent near the wheel well. Some of the lower bumper brackets may be bent, but it is not clear whether all of this damage came from this impact. The repair plan calls for replacing the bumper cover and taillight, straightening the trunk lid, and refinishing the affected panels. The labor hours are a little high for this scope of work and should be reviewed. The invoices show no repeated charges. No earlier damage to the vehicle is known.