Harris Auto Repair

740 Cynthia Village Suite 005
Pearland, TX
Phone 832-555-2786

Repair Estimate

Estimate number:	EST-839413
Estimate date:	7-2-24
Customer:	Diane Jones
Phone:	281-555-9671
Insurance claim:	C-1050
Vehicle:	2016 Honda Civic
VIN:	AJMNWV211GLHA6239
License plate:	608BP

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$951.17
Right front door shell	1	$788.75
Left front fender	1	$768.16
Body labor	25.2 hrs	$1,715.37
Paint and materials		$1,084.46
TOTAL		$5,307.91

Appraiser remarks

The rear bumper cover is cracked across the left corner, with the left quarter panel creased and the tail lamp housing broken. The damage sits where a low-speed reversing impact would place it, and it lines up well with what was described at intake. The proposed plan is to replace the bumper cover, straighten and refinish the quarter panel, and fit a new tail lamp assembly. Labor hours are reasonable for this scope, and the parts listed match the visible damage. No prior damage to this vehicle is on record, and the invoices show no repeated charges for the same work.