Edwards Auto Body

465 Terry Plaza Apt. 366
Pearland, TX
Phone 832-555-6804

Repair Estimate

Estimate number:	EST-504396
Estimate date:	2024-08-04
Customer:	Tammy Barrett
Phone:	281-555-6448
Insurance claim:	C-1051
Vehicle:	2021 Hyundai Elantra
VIN:	UPWJNYMM92MLF9955
License plate:	MES-1714

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$1,456.52
Left quarter panel	1	$913.62
Left front fender	1	$1,174.64
Body labor	56.4 hrs	$2,706.03
Paint and materials		$1,040.84
TOTAL		$7,291.65

Appraiser remarks

The rear quarter panel and left taillight assembly show crushed metal and cracked lens consistent with a rear impact while turning left. Paint transfer and the direction of the deformation line up with the account given, and no earlier damage to the vehicle is known from the records reviewed. The shop's invoices show no repeated charges. The proposed plan replaces the quarter panel, refinishes the adjacent door, and swaps the taillight unit. Labor hours run slightly high for this scope of work, so the shop should be asked to justify the hours before approval.