Rogers Auto Repair

23623 Robert Isle
League City, TX
Phone 346-555-0366

Repair Estimate

Estimate number:	EST-393489
Estimate date:	2025-07-03
Customer:	Mary Warren
Phone:	832-555-6182
Insurance claim:	C-1053
Vehicle:	2021 Chevrolet Malibu
VIN:	4USW21NH7F9FD6966
License plate:	007 1580

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$735.62
Front bumper cover	1	$705.81
Hood panel	1	$588.16
Body labor	17.3 hrs	$1,173.80
Paint and materials		$767.58
TOTAL		$3,970.97

Appraiser remarks

The rear bumper cover is cracked across the center, with the left tail lamp assembly broken and the trunk lid edge scuffed where the impact landed. Damage patterns on the quarter panel line up with the reported contact point, and the pattern is consistent with a low-speed strike from behind. Repair plan: replace the bumper cover, install a new tail lamp assembly, refinish the trunk lid edge, and blend adjacent paint. The labor hours listed are in line with the work described. The invoices submitted show each line item billed once, with no repeated charges. Nothing in our records or the owner's account points to earlier damage in this area, so the estimate is recommended as written.