Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-441008
Estimate date:	June 9, 2025
Customer:	Blake White
Phone:	832-555-6528
Insurance claim:	C-1055
Vehicle:	2024 Jeep Cherokee
VIN:	DHKWJLBE5EAUH5163
License plate:	QTP 100

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,515.05
Right front door shell	1	$1,534.62
Left front fender	1	$1,059.05
Body labor	44.1 hrs	$2,996.05
Paint and materials		$1,816.94
TOTAL		$8,921.71

Appraiser remarks

The vehicle was inspected at the body shop following a collision that occurred while the insured was turning left. The rear quarter panel and bumper cover show fresh deformation and paint transfer cnosistent with this impact. Some older scratches on the lower door are present, and these may pre-date the crash, so it is not clear whether all of the observed damage came from this event. The repair plan calls for replacing the bumper cover, straightening the quarter panel, and refinishing the affected areas. The labor hours listed fit the damage observed. The itemized charges show no repeated entries, and the estimate is recommended for approval once the older marks are noted separately.