King Auto Repair

184 Rodriguez Mews
Pearland, TX
Phone 346-555-0482

Repair Estimate

Estimate number:	EST-221634
Estimate date:	November 7, 2023
Customer:	Timothy Middleton
Phone:	832-555-2883
Insurance claim:	C-1056
Vehicle:	2011 Chevrolet Malibu
VIN:	
License plate:	218-KQR

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$784.26
Headlamp assembly	1	$727.20
Right front door shell	1	$596.07
Body labor	26.8 hrs	$1,287.07
Paint and materials		$628.90
TOTAL		$4,023.50

Appraiser remarks

The vehicle presents front-end damage consistent with the reported low-speed head-on impact, including a cracked bumper cover, a bent upper radiator support, and a displaced hood latch. The repair plan calls for replacing the bumper cover and hood latch, straightening the support, and refinishing the affected panels. Shop invoices reviewed so far show no duplicaetd line items. Labor hours appear slightly high for the extent of this damage and should be checked against the standard time guide. A few older scratches on the lower door area may predate this incident and should be noted separately from the repair scope.