# Hernandez Auto Body

9176 Jennifer Lights
League City, TX
Phone 346-555-3201

## Repair Estimate

| | |
|---|---|
| **Estimate number:** | EST-779240 |
| **Estimate date:** | August 22, 2023 |
| **Customer:** | Justin Anderson |
| **Phone:** | 713-555-5313 |
| **Insurance claim:** | C-1057 |
| **Vehicle:** | 2015 Ford F-150 |
| **VIN:** | FYXJYW1440MFB7881 |
| **License plate:** | FC-8082 |

### Estimate details

| Description | Qty / Hours | Amount |
|---|---|---|
| Trunk lid | 1 | $1,940.44 |
| Rear body panel | 1 | $1,310.55 |
| Left tail lamp assembly | 1 | $902.66 |
| Body labor | 46.1 hrs | $3,134.78 |
| Paint and materials | | $1,389.85 |
| TOTAL | | $8,678.28 |

### Appraiser remarks

The rear bumper cover is cracked across its center section, the tail lamp assembly is broken, and the trunk lid shows a crease running toward the left quarter panel. The lower bumper reinforcement appears bent, which supports the repair plan to replace the cover, lamp assembly, and reinforcement and to refinish the trunk lid and adjacent panel. Labor hours litsed on the estimate fit the damage described. Some of the scratches on the lower rear panel look older than this impact and may be unrelated, so they will be marked separately. It is not yet clear whether all of the damage came from this collision. Two similar charges dated the same day are being checked before the estimate is finalized.