Calhoun Auto Repair

81219 Emma Freeway
Conroe, TX
Phone 713-555-9399

Repair Estimate

Estimate number:	EST-639624
Estimate date:	2023-08-28
Customer:	Kristina Brown
Phone:	346-555-6889
Insurance claim:	C-1059
Vehicle:	2018 Jeep Cherokee
VIN:	24NDSTDC3DG902763
License plate:	283 WM7

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$1,291.80
Left quarter panel	1	$1,101.62
Hood panel	1	$1,228.53
Body labor	44.8 hrs	$3,044.86
Paint and materials		$1,185.55
TOTAL		$7,852.36

Appraiser remarks

Front bumper cover cracked across the center with the reinforcement bar bent at the left mounting point, and the left headlamp assembly broken at its housing. The hood shows a shallow crease that lines up with the bumper damage, and the radiator support has minor bending on the same side. The pattern of damage is consistent with the frontal impact reported. Repair plan calls for replacing the bumper cover, reinforcement bar, and headlamp, with straightening of the radiator support and refinishing of the hood. Labor hours are in line with the work described. The invoices show no duplicated charges. Nothing in the records points to earlier damage to this vehicle.