Moore Auto Body

06797 Johnson Heights
Katy, TX
Phone 346-555-1349

Repair Estimate

Estimate number:	EST-267685
Estimate date:	12-16-23
Customer:	Jessica Chapman
Phone:	832-555-9673
Insurance claim:	C-1061
Vehicle:	2019 Chevrolet Malibu
VIN:	RREANRWDXZVHD2234
License plate:	019-NVM

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$1,229.34
Right front door shell	1	$1,051.94
Headlamp assembly	1	$930.31
Body labor	48.3 hrs	$2,316.51
Paint and materials		$1,296.96
TOTAL		$6,825.06

Appraiser remarks

The rear bumper cover is cracked across the left corner, with the left tail lamp housing broken and the trunk lid edge scuffed. The pattern of damage is mostly consistent with the low-speed impact described in the loss report, and no prior damage to this vehicle is known from the file. The repair plan calls for replacing the bumper cover and lamp assembly and refinishing the trunk edge. The labor hours on the shop's estimate run a little high for this scope of work, so I recommend a line-by-line review before approval. The invoices provided show no repeated charges.